



SuperSystems
incorporated

SIMPLE DEW DIGITAL DEW POINT ANALYZER OPERATIONS MANUAL

Super Systems Inc.
7205 Edington Drive
Cincinnati, OH 45249
513-772-0060
Fax: 513-772-9466
www.supersystems.com

Simple Dew Digital Dew Point Analyzer Operations Manual

Super Systems Inc.

USA Office
Corporate Headquarters
7205 Edington Drive
Cincinnati, OH 45249
Phone: (513) 772-0060
<http://www.supersystems.com>

Super Systems Europe

Units 3 & 4, 17 Reddicap Trading Estate,
Sutton Coldfield, West Midlands
B75 7BU
UNITED KINGDOM
Phone: +44 (0) 121 329 2627
<http://www.supersystemseurope.com>

Super Systems México

Sistemas Superiores Integrales S de RL de CV
Calle 3 Int.: 11.
Zona Ind. Benito Juarez
Querétaro, Qro. Méx.
C.P.: 76120
Phone: +52 (442) 210 2459
<http://www.supersystems.com.mx>

Super Systems China

No. 335 XianXia Road
Room 308
Shanghai, CHINA
200336
Phone: +86 21 5206 5701/2
<http://www.supersystems.com>

Table of Contents

Introduction.....	4
Specifications.....	4
Warnings.....	4
Startup	4
Operation.....	5
Instrument Damage.....	5
What Is Dew Point?	6
How It Works.....	6
Maintenance/Safety Issues.....	7
Factory Calibration.....	7
Field Calibration.....	7
Replacement Parts	11
Returning the Unit to SSi	11
Warranty.....	13
Revision History	14
Appendix A: Determining the Sensor Temperature in °F.....	15
Appendix B: Determining the Sensor Temperature in °C	16
Appendix C: Determining the Dew Point in °F.....	17
Appendix D: Determining the Dew Point in °C.....	18

Introduction

Thank you for selecting Super Systems Inc. and the Simple Dew as your source for accurate dew point measurements. The Simple Dew unit is a digital dew point analyzer for standard range (greater than 0°F or -18°C) measurement. Typical uses of the Simple Dew include measurement of endothermic atmospheres (with endothermic generators) and nitrogen/methanol atmospheres, as well as use with plant air systems.

Carefully unpack the Simple Dew - Dew Point Analyzer. If there are any signs of shipping damage, notify SSI and the shipper immediately.

Specifications

Measurement Range:	0 to +80°F (-18 to +27°C)
Temperature Range:	0 to +120°F (-18 to +49°C)
Power Supply:	115 to 230 VAC (universal input)—for Part No. 13134 24VDC input—for Part No. 13136
Retransmission Output:	0-1 Volt (range is -50 to +80°F)
Size (Closed Case):	15.25" x 9" x 6.25" (approximately)
Weight:	8.2 lbs (3.7 kg)

Warnings

Although it is intended for use in an industrial environment, the Simple Dew is a sensitive piece of analysis equipment. Care should be taken not to drop the analyzer or to operate it in a manner inconsistent with its intended use.

- Open all sample ports and remove all soot and/or moisture from the lines prior to attaching the sample tubing for the first time.
- The analyzer should be stored at ambient temperature (65-80°F or 18-27°C) for at least two hours prior to operation.
- If the unit is to be returned to SSI for service or any other reason, protect the instrument with at least four inches of foam or other impact-absorbing material on all sides and place it in an appropriately sized cardboard box.
- This unit is not designed to measure the dew points in corrosive gases, such as Ammonia, SO₃, Chlorine, and HCL.
- Please read and understand this Product Manual before operating the unit.

Failure to comply with these conditions may cause damage to the unit that will not be covered under the warranty. Super Systems Inc. is not responsible for damage to this unit caused by disregard of these warnings, neglect, or misuse.

Startup

The Simple Dew unit was calibrated before it was shipped from Super Systems Inc. You can begin typical operation as soon as the unit has been allowed to stabilize in a temperature similar to the temperature in the heat treating department. This stabilization is particularly important for units that may have been sitting overnight in a delivery vehicle in freezing

weather. Rapid temperature change can cause condensation on the sensor which will cause the unit to temporarily display inaccurate readings.

Operation

The use of the Simple Dew is somewhat dependent upon the application. For connection to an endothermic generator, no pump is required since the sample gas is under positive pressure. If this instrument is to be used on a furnace or other non-positive pressure application, an external sample pump will be required to deliver the gas to the sensor.

Be sure that the filter (mounted to the bottom of the instrument) is clean and functional, since high accumulations of soot can hold moisture and influence the dew point measurement. It will also prevent soot and other contaminants from entering the unit and damaging the sensor. The optimum flow rate of the sample gas should be between 1.5 and 2.0 Standard Cubic Feet per Hour (SCFH), although a flow rate as low as 1.0 SCFH is acceptable. If the unit is reading less than 1.0 SCFH, verify that there are no obstructions to the flow such as a clogged sample line or filter, or a poorly adjusted knob on the Simple Dew's flow meter.

Heat Treat Furnace Sampling: A gas sample must be extracted from the process using an external pump. The sample tube from which the sample is taken out of the furnace should extend into the furnace past the HOT face of the refractory. For accurate results, a designated sample port should be used to extract the sample. SSI offers two versions of sample port assemblies (part numbers 20263 and 20264) which are ideal for this purpose. If a designated sample port is not available, then a clean "burn-off" port on a Gold Probe™, an industry leading oxygen sensor for atmosphere control, can be used. Readings taken from the burn-off port on a probe may be artificially high due to the presence of soot in the probe sheath.

Endothermic Generator Sampling: For applications under pressure, the flow is controlled by the small restriction valve on the flow meter. A flow rate between 1.5 and 2.0 SCFH is ideal. The sample should be taken from the endothermic gas manifold after the gas has been cooled.

NOTE: Allow the sample port to blow out any soot and / or water before connecting the sample tube. Failure to do so will result in inaccurate readings and expose the sensor to potential damage.

Instrument Damage

The main causes of damage to the Simple Dew are the ingestion of soot and the ingestion of water. Both of these contaminants will cause erroneous readings in the short term, and cause long-term damage to the sensor and internal components.

Soot / Particulate Contaminants

When taking a sample from a furnace or a generator, care should be taken to reduce the amount of soot that enters the instrument. The filter will trap these particles, but cleaning the sample line before attaching the Simple Dew will increase the life of the filter. Furnace ports can be burned off by pumping air through them while hot, or by removing them from the heat and mechanically cleaning them. Generator ports should be opened before the instrument is attached to allow any particulate buildup to be blown out. It is also helpful to tap on the port while it is being blown out to eject any loose particles before the instrument is attached.

If soot is allowed to collect on the dew point sensor in the instrument, it could result in higher readings. This soot will also retain moisture than can corrode the sensor over time. The sensor

tip can be cleaned by carefully removing it from the sample block (see Section 2.0 of the Field Calibration instructions) and rinsing it in isopropyl alcohol. The power should be off while this is done, and the power should remain off for at least 30 minutes after this procedure to allow all of the alcohol to completely evaporate.

Water / Moisture Contamination

When a furnace or generator is being started up or cooled down, the resulting gases will contain unusually high amounts of CO₂. When these gases cool, moisture will precipitate out and become condensation inside the sample tubing assembly. Even if the furnace or generator is operating normally, residual moisture may still be present in the sample tube or plumbing system. In the same way that the ports are checked for soot (see above) they should be checked for moisture before attaching the instrument. This is especially important when taking a sample from a generator, since the sample port is usually preceded by a significant amount of plumbing. All traces of moisture should be eliminated before attaching the instrument. Failure to do so will result in erroneous measurements and could result in damage to the analyzer.

The first signs of moisture in the instrument will be visible condensation collecting in the bowl filter and an unusually high dew point. The upper range of the sensor is +80°F, so if that value is displayed on the instrument it is probably due to the presence of moisture. If this moisture is not removed, it will cause the sensor tip to corrode and will eventually require the sensor to be replaced.

To remove moisture from the instrument, the filter should be removed from the instrument (since it will probably be wet) and an inert gas such as Nitrogen or Argon should then be flowed through the instrument for as much time as it takes to dry out. This dry-out time will depend on the amount of moisture present in the instrument. The condition of the sensor can be monitored by periodically reading the dew point from the display and watching the value decrease over time. To test if it is operating properly, verify the ambient dew point against a web-based weather station that will report the ambient dew point for your area. If the displayed reading is within three degrees of the reported dew point when the instrument is taken outside, then all of the moisture has probably been successfully removed. The wet filter and sample tubing can be re-attached after they have been completely dried out. The filter element will regain all of its original filtering properties after it has dried out.

To prevent the possibility of moisture damaging the instrument, be sure that the measured dew point is below ambient levels before it is stored. If necessary, Nitrogen or Argon can be used to purge the instrument after use.

What Is Dew Point?

Dew point can be defined as the temperature at which the water vapor pressure of the gas equals the saturated water vapor pressure. In other words, it is the temperature at which condensation will just begin to occur as the gas is cooled. Dew point and relative humidity are not the same measurement. Relative humidity is the amount of water vapor in the air compared to the amount the air could hold if it was totally saturated, and it is expressed as a percentage, not a temperature. To determine dew point, two main variables are required: Relative Humidity and Temperature. The Simple Dew measures both variables to compute the dew point.

How It Works

The dew point sensor is a “dielectric ceramic” that varies its electrical capacitance with changes in relative humidity. The sensor is mounted in a short probe, which is installed in a T-fitting that allows the sample gas to flow past the sensor. The tip of this probe contains the dielectric ceramic relative humidity (RH) sensor, as well as a built in temperature sensor to determine its dry bulb temperature. Information from both of these sensors is used to compute the resultant dew point.

Maintenance/Safety Issues

Maintaining proper sensor temperature will prevent the premature failure of the sensor. The operating temperature of the sensor should remain below 130° F (54°C) at all times. To determine the sensor temperature, measure the voltage between pins 5(+) and 9(-) on the microprocessor board. The voltage will be between 0 and 1VDC. Use the chart in Appendix A to determine the temperature in °F, or use Appendix B to determine the temperature in °C. If this temperature shows in excess of 130°F (54°C), the length of sample tubing should be increased to allow for adequate cooling of the sample before it passes the sensor tip.

Factory Calibration

Calibration of the sensor is recommended annually. SSI's initial calibration is performed in our ISO/IEC 17025 certified laboratory, and includes an NIST traceable “Certificate of Calibration”. Any calibration performed at SSI will be NIST traceable and will have documentation of ISO/IEC 17025 certification. The certificate also indicates the accuracy of the analyzer before and after calibration. Please contact Super Systems, Inc. at (513) 772-0060 for more information regarding this service.


Field Calibration

It is also possible to calibrate the Simple Dew in the field, which will require one of two optional calibration kits. One calibration kit is NIST traceable (Part No. 31425); one kit is non-traceable (Part No. 31030). To perform this calibration, you will need a calibration kit and a voltmeter that will allow you to measure between 0 and 1 volt DC. Since there is no display on the instrument itself, the voltages from the sensor circuit board will have to be translated into temperature and dew point measurements for the purpose of verifying the calibration. The instructions for doing this are contained in this document along with reference charts to aid in the interpretation of the voltages.

The calibration kit consists of two bottles of saturated salt solution in which each bottle generates a precise relative humidity percentage (R.H.%) value. One bottle is 11.3% R.H., and the other is 75.3% R.H. These two specific calibration points are already pre-programmed into the microprocessor board.

1.0 Locate the key components within the unit

- 1.1 The **microprocessor board** contains three very small buttons that are used for calibration. Two are next to one another, and they are marked “75.3%” and “11.3%”, while the other has no label. The unmarked button is the “Calibrate” button. The approximate locations of each button are shown on this diagram:



- 1.2 The **sensor-sampling chamber** is the gray rectangular box with brass barb fittings on either side with a black plastic gland protruding from the center.
- 1.3 The **sensor probe** is positioned in the sensor-sampling chamber. It is held in place by the nut on the black plastic gland.
- 2.0 Remove the sensor probe from the sensor sampling chamber.
 - 2.1 Loosen the black plastic gland nut and slowly slide the sensor probe out through the airtight seal. Care must be taken when removing this sensor probe, since the tip is very delicate and can be easily damaged if it is mishandled. Note that the probe has white mark at the wire entry point, which must be aligned with corresponding white mark in plastic gland when it is re-inserted in the sampling chamber.
- 3.0 Install the sensor probe into the 75.3% salt solution.
 - 3.1 Slip the black sensor gland (supplied in the calibration kit) over the sensor probe with the sensor tip protruding from the threaded end of the gland and the sensor wires being flush with the top of the rubber o-ring in the gland. Tighten the gland around the sensor. This does not need to be done with a wrench or other tools, but it does need to be tight enough to prevent ambient air from contaminating the humidity level of the sampling chamber.
 - 3.2 Remove the cap of the 75.3% salt solution and install the sensor gland (with the sensor) into the salt solution. To increase the life of the calibration salts, an effort should be made to minimize the amount of time that the salt solution is exposed to the ambient air.
- 4.0 Allow the sensor to reach equilibrium with the calibration salt.

Simple Dew Digital Dew Point Analyzer Operations Manual

- 4.1 Leave the sensor in the calibration salt for a minimum of eighteen (18) hours. It is acceptable to leave the sensor in the salt solution for a longer period of time, even a few days, if desired.
- 5.0 Begin the 75.3% (Span) calibration process.
 - 5.1 After leaving the sensor in the salt for at least eighteen (18) hours, turn the unit on (if it isn't on already).
 - 5.2 Simultaneously press the "75.3%" and "Calibration" buttons on the microprocessor board.
- 6.0 Verify the 75.3% (Span) calibration.
 - 6.1 Leave the sensor in the 75.3%RH calibration salt.
 - 6.2 Record the temperature and the dew point of the sensor. Since there is no display on the instrument, you will need to measure the voltage from the microprocessor board and translate that into the appropriate measurement.
 - 6.2.1 To determine the sensor temperature, measure the voltage between pins 5(+) and 9(-) on the microprocessor board. The voltage will be between 0 and 1VDC. Use the chart in Appendix A to determine the temperature in °F, or use Appendix B to determine the temperature in °C.
 - 6.2.2 Temporarily record the sensor temperature.
 - 6.3 Look up this temperature in Appendix "C" (Determining the Dew Point in °F) or Appendix "D" (Determining the Dew Point in °C). Appendix C will show the temperature values in Fahrenheit, and Appendix D will show the temperature values in Celsius.
 - 6.4 Next to the appropriate sensor temperature, note the number in the corresponding column titled "75.3%". This will match the measured dew point, which can be verified wherever the dew point is displayed.
- 7.0 After the 75.3% (Span) calibration has been completed, remove the sensor from the calibration salt and replace the cap on the salt.
 - 7.1 Leave the sensor probe in the gland and while the unit is still on, allow it to achieve equilibrium at the ambient atmosphere in the room. This is accomplished by simply leaving the sensor exposed to ambient air for between two and three minutes. You will know when this has been accomplished when the numbers on the display begin to stabilize.
- 8.0 Install the sensor probe into the 11.3% salt solution.

- 8.1 Remove the cap of the 11.3% salt solution and install the sensor gland (with the sensor) into the salt solution. To increase the life of the calibration salts, an effort should be made to minimize the amount of time that the salt solution is exposed to the ambient air.
- 9.0 Allow the sensor to reach equilibrium with the calibration salt.
 - 9.1 Leave the sensor in the calibration salt for a minimum of 24 hours. It is acceptable to leave the sensor in the salt solution for a longer period of time, even a few days, if desired.
- 10.0 Begin the 11.3% (Zero) calibration process
 - 10.1 After leaving the sensor in the salt for at least twenty-four (24) hours, turn the unit on (if it isn't on already).
 - 10.2 Simultaneously press the "11.3%" and "Calibration" buttons on the microprocessor board.
- 11.0 Verify the 11.3% (Zero) calibration
 - 11.1 Leave the sensor in the 11.3%RH calibration salt
 - 11.2 Record the temperature and the dew point of the sensor. Since there is no display on the instrument, you will need to measure the voltage from the microprocessor board and translate that into the appropriate measurement.
 - 11.2.1 To determine the sensor temperature, measure the voltage between pins 5(+) and 9(-) on the microprocessor board. The voltage will be between 0 and 1VDC. Use the chart in Appendix A to determine the temperature in °F, or use Appendix B to determine the temperature in °C.
 - 11.2.2 Temporarily record the sensor temperature.
 - 11.3 Look up this temperature in Appendix "C" (Determining the Dew Point in °F) or Appendix "D" (Determining the Dew Point in °C). Appendix C will show the temperature values in Fahrenheit, and Appendix D will show the temperature values in Celsius.
 - 11.4 Next to the appropriate temperature, note the number in the corresponding column titled "11.3%". This will match the measured dew point, which can be verified wherever the dew point is displayed.
- 12.0 After the 11.3% (Zero) calibration has been completed, remove the sensor from the calibration salt and replace the cap on the salt.

12.1 After the 11.3% (Zero) calibration has been completed, remove the sensor from the calibration salt and replace the cap.

13.0 Re-assemble the unit

13.1 After the calibration process has been completed, remove the sensor probe from the gland and return it to the sensor-sampling chamber, taking care to position it properly. The white mark on the sensor probe should face towards the inlet tubing. If the white mark is not visible, then it should be placed so the sample flow directly strikes the face of the mirror on the sensor tip. In other words, the mirror should face the incoming gas stream.

13.2 Hand-tighten the black sensor gland to prevent air from leaking out of the sampling chamber.

14.0 Make sure that all caps are replaced on the calibration salts, and return the instrument to service.

Replacement Parts

Description	Part Number
Factory Calibration	65010
Calibration Kit (non-traceable)	31030
Calibration Kit (NIST traceable)	31425
Bowl Filter	37048
Bowl Filter Element	31027
Dew Point Sensor	31038
Sensor Sampling Block	20192
Sample Tube	20263
Sample Tube (With High-Temp Filter)	20264
Complete Units	
Simple Dew Unit (with Power Supply)	13134
Simple Dew Unit (without Power Supply)	13136

Returning the Unit to SSi

This analyzer contains some components that may require periodic replacement based on the amount of use that the unit experiences and the methods in which it is used. If service on the unit is necessary, it should be sent back to Super Systems, Inc. in the original packaging for repair. If the original packaging is not available, the analyzer should be surrounded by impact-absorbing materials and placed in a box. It is the responsibility of the shipper to ensure that the Simple Dew arrives at SSi undamaged.

Simple Dew Digital Dew Point Analyzer Operations Manual

Before shipping the analyzer, please call (513) 772-0060 to receive a Return Materials Authorization (RMA) number. The shipping address that should be used for returns is:

**Super Systems, Inc.
ATTN: RMA #XXXX
7205 Edington Drive
Cincinnati, OH 45249**

Warranty

Limited Warranty for Super Systems Products:

The Limited Warranty applies to new Super Systems Inc. (SSI) products purchased direct from SSI or from an authorized SSI dealer by the original purchaser for normal use. SSI warrants that a covered product is free from defects in materials and workmanship, with the exceptions stated below.

The limited warranty does not cover damage resulting from commercial use, misuse, accident, modification or alteration to hardware or software, tampering, unsuitable physical or operating environment beyond product specifications, improper maintenance, or failure caused by a product for which SSI is not responsible. There is no warranty of uninterrupted or error-free operation. There is no warranty for loss of data—you must regularly back up the data stored on your product to a separate storage product. There is no warranty for product with removed or altered identification labels. SSI DOES NOT PROVIDE ANY OTHER WARRANTIES OF ANY KIND, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OR CONDITIONS OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE. SOME JURISDICTIONS DO NOT ALLOW THE LIMITATION OF IMPLIED WARRANTIES, SO THIS LIMITATION MAY NOT APPLY TO YOU. SSI is not responsible for returning to you product which is not covered by this limited warranty.

If you are having trouble with a product, before seeking limited warranty service, first follow the troubleshooting procedures that SSI or your authorized SSI dealer provides.

SSI will replace the PRODUCT with a functionally equivalent replacement product, transportation prepaid after PRODUCT has been returned to SSI for testing and evaluation. SSI may replace your product with a product that was previously used, repaired and tested to meet SSI specifications. You receive title to the replaced product at delivery to carrier at SSI shipping point. You are responsible for importation of the replaced product, if applicable. SSI will not return the original product to you; therefore, you are responsible for moving data to another media before returning to SSI, if applicable. Data Recovery is not covered under this warranty and is not part of the warranty returns process. SSI warrants that the replaced products are covered for the remainder of the original product warranty or 90 days, whichever is greater.

Revision History

Rev.	Description	Date	MCO#
-	First Release	03-06-2009	N/A
A	Manual updated to current standard format. Introduction updated. Specifications updated to include power requirements specified based on Simple Dew unit. Calibration instructions updated to include two calibration kit options. Replacement parts list updated, including the addition of two calibration kits and two complete units.	04-13-2015	2158

Simple Dew Digital Dew Point Analyzer Operations Manual

Appendix A: Determining the Sensor Temperature in °F

When the DC voltage between 5(+) and 8(-) is:	Then the sensor temperature (°F) is:	When the DC voltage between 5(+) and 8(-) is:	Then the sensor temperature (°F) is:	When the DC voltage between 5(+) and 8(-) is:	Then the sensor temperature (°F) is:
0.3472	67.0	0.3806	79.0	0.4139	91.0
0.3478	67.2	0.3811	79.2	0.4144	91.2
0.3483	67.4	0.3817	79.4	0.4150	91.4
0.3489	67.6	0.3822	79.6	0.4156	91.6
0.3494	67.8	0.3828	79.8	0.4161	91.8
0.3500	68.0	0.3833	80.0	0.4167	92.0
0.3506	68.2	0.3839	80.2	0.4172	92.2
0.3511	68.4	0.3844	80.4	0.4178	92.4
0.3517	68.6	0.3850	80.6	0.4183	92.6
0.3522	68.8	0.3856	80.8	0.4189	92.8
0.3528	69.0	0.3861	81.0	0.4194	93.0
0.3533	69.2	0.3867	81.2	0.4200	93.2
0.3539	69.4	0.3872	81.4	0.4206	93.4
0.3544	69.6	0.3878	81.6	0.4211	93.6
0.3550	69.8	0.3883	81.8	0.4217	93.8
0.3556	70.0	0.3889	82.0	0.4222	94.0
0.3561	70.2	0.3894	82.2	0.4228	94.2
0.3567	70.4	0.3900	82.4	0.4233	94.4
0.3572	70.6	0.3906	82.6	0.4239	94.6
0.3578	70.8	0.3911	82.8	0.4244	94.8
0.3583	71.0	0.3917	83.0	0.4250	95.0
0.3589	71.2	0.3922	83.2	0.4256	95.2
0.3594	71.4	0.3928	83.4	0.4261	95.4
0.3600	71.6	0.3933	83.6	0.4267	95.6
0.3606	71.8	0.3939	83.8	0.4272	95.8
0.3611	72.0	0.3944	84.0	0.4278	96.0
0.3617	72.2	0.3950	84.2	0.4283	96.2
0.3622	72.4	0.3956	84.4	0.4289	96.4
0.3628	72.6	0.3961	84.6	0.4294	96.6
0.3633	72.8	0.3967	84.8	0.4300	96.8
0.3639	73.0	0.3972	85.0	0.4306	97.0
0.3644	73.2	0.3978	85.2	0.4311	97.2
0.3650	73.4	0.3983	85.4	0.4317	97.4
0.3656	73.6	0.3989	85.6	0.4322	97.6
0.3661	73.8	0.3994	85.8	0.4328	97.8
0.3667	74.0	0.4000	86.0	0.4333	98.0
0.3672	74.2	0.4006	86.2	0.4339	98.2
0.3678	74.4	0.4011	86.4	0.4344	98.4
0.3683	74.6	0.4017	86.6	0.4350	98.6
0.3689	74.8	0.4022	86.8	0.4356	98.8
0.3694	75.0	0.4028	87.0	0.4361	99.0
0.3700	75.2	0.4033	87.2	0.4367	99.2
0.3706	75.4	0.4039	87.4	0.4372	99.4
0.3711	75.6	0.4044	87.6	0.4378	99.6
0.3717	75.8	0.4050	87.8	0.4383	99.8
0.3722	76.0	0.4056	88.0	0.4389	100.0
0.3728	76.2	0.4061	88.2	0.4394	100.2
0.3733	76.4	0.4067	88.4	0.4400	100.4
0.3739	76.6	0.4072	88.6	0.4406	100.6
0.3744	76.8	0.4078	88.8	0.4411	100.8
0.3750	77.0	0.4083	89.0	0.4417	101.0
0.3756	77.2	0.4089	89.2	0.4422	101.2
0.3761	77.4	0.4094	89.4	0.4428	101.4
0.3767	77.6	0.4100	89.6	0.4433	101.6
0.3772	77.8	0.4106	89.8	0.4439	101.8
0.3778	78.0	0.4111	90.0	0.4444	102.0
0.3783	78.2	0.4117	90.2	0.4450	102.2
0.3789	78.4	0.4122	90.4	0.4456	102.4
0.3794	78.6	0.4128	90.6	0.4461	102.6
0.3800	78.8	0.4133	90.8	0.4467	102.8

Simple Dew Digital Dew Point Analyzer Operations Manual

Appendix B: Determining the Sensor Temperature in °C

When the DC voltage between 5(+) and 8(-) is:	Then the sensor temperature (°C) is:	When the DC voltage between 5(+) and 8(-) is:	Then the sensor temperature (°C) is:	When the DC voltage between 5(+) and 8(-) is:	Then the sensor temperature (°C) is:
0.3472	19.4	0.3806	26.1	0.4139	32.8
0.3478	19.6	0.3811	26.2	0.4144	32.9
0.3483	19.7	0.3817	26.3	0.4150	33.0
0.3489	19.8	0.3822	26.4	0.4156	33.1
0.3494	19.9	0.3828	26.6	0.4161	33.2
0.3500	20.0	0.3833	26.7	0.4167	33.3
0.3506	20.1	0.3839	26.8	0.4172	33.4
0.3511	20.2	0.3844	26.9	0.4178	33.6
0.3517	20.3	0.3850	27.0	0.4183	33.7
0.3522	20.4	0.3856	27.1	0.4189	33.8
0.3528	20.6	0.3861	27.2	0.4194	33.9
0.3533	20.7	0.3867	27.3	0.4200	34.0
0.3539	20.8	0.3872	27.4	0.4206	34.1
0.3544	20.9	0.3878	27.6	0.4211	34.2
0.3550	21.0	0.3883	27.7	0.4217	34.3
0.3556	21.1	0.3889	27.8	0.4222	34.4
0.3561	21.2	0.3894	27.9	0.4228	34.6
0.3567	21.3	0.3900	28.0	0.4233	34.7
0.3572	21.4	0.3906	28.1	0.4239	34.8
0.3578	21.6	0.3911	28.2	0.4244	34.9
0.3583	21.7	0.3917	28.3	0.4250	35.0
0.3589	21.8	0.3922	28.4	0.4256	35.1
0.3594	21.9	0.3928	28.6	0.4261	35.2
0.3600	22.0	0.3933	28.7	0.4267	35.3
0.3606	22.1	0.3939	28.8	0.4272	35.4
0.3611	22.2	0.3944	28.9	0.4278	35.6
0.3617	22.3	0.3950	29.0	0.4283	35.7
0.3622	22.4	0.3956	29.1	0.4289	35.8
0.3628	22.6	0.3961	29.2	0.4294	35.9
0.3633	22.7	0.3967	29.3	0.4300	36.0
0.3639	22.8	0.3972	29.4	0.4306	36.1
0.3644	22.9	0.3978	29.6	0.4311	36.2
0.3650	23.0	0.3983	29.7	0.4317	36.3
0.3656	23.1	0.3989	29.8	0.4322	36.4
0.3661	23.2	0.3994	29.9	0.4328	36.6
0.3667	23.3	0.4000	30.0	0.4333	36.7
0.3672	23.4	0.4006	30.1	0.4339	36.8
0.3678	23.6	0.4011	30.2	0.4344	36.9
0.3683	23.7	0.4017	30.3	0.4350	37.0
0.3689	23.8	0.4022	30.4	0.4356	37.1
0.3694	23.9	0.4028	30.6	0.4361	37.2
0.3700	24.0	0.4033	30.7	0.4367	37.3
0.3706	24.1	0.4039	30.8	0.4372	37.4
0.3711	24.2	0.4044	30.9	0.4378	37.6
0.3717	24.3	0.4050	31.0	0.4383	37.7
0.3722	24.4	0.4056	31.1	0.4389	37.8
0.3728	24.6	0.4061	31.2	0.4394	37.9
0.3733	24.7	0.4067	31.3	0.4400	38.0
0.3739	24.8	0.4072	31.4	0.4406	38.1
0.3744	24.9	0.4078	31.6	0.4411	38.2
0.3750	25.0	0.4083	31.7	0.4417	38.3
0.3756	25.1	0.4089	31.8	0.4422	38.4
0.3761	25.2	0.4094	31.9	0.4428	38.6
0.3767	25.3	0.4100	32.0	0.4433	38.7
0.3772	25.4	0.4106	32.1	0.4439	38.8
0.3778	25.6	0.4111	32.2	0.4444	38.9
0.3783	25.7	0.4117	32.3	0.4450	39.0
0.3789	25.8	0.4122	32.4	0.4456	39.1
0.3794	25.9	0.4128	32.6	0.4461	39.2
0.3800	26.0	0.4133	32.7	0.4467	39.3

Appendix C: Determining the Dew Point in °F

Sensor Temp (°F)	Percent RH	
	11.3%	75.3%
67.0	11.38	58.94
67.2	11.54	59.13
67.4	11.69	59.32
67.6	11.85	59.52
67.8	12.00	59.71
68.0	12.16	59.90
68.2	12.31	60.09
68.4	12.47	60.29
68.6	12.63	60.48
68.8	12.78	60.67
69.0	12.94	60.86
69.2	13.09	61.06
69.4	13.25	61.25
69.6	13.40	61.45
69.8	13.56	61.64
70.0	13.71	61.83
70.2	13.87	62.03
70.4	14.02	62.22
70.6	14.18	62.41
70.8	14.33	62.60
71.0	14.49	62.80
71.2	14.65	62.99
71.4	14.80	63.18
71.6	14.96	63.38
71.8	15.11	63.57
72.0	15.27	63.76
72.2	15.42	63.96
72.4	15.58	64.15
72.6	15.73	64.34
72.8	15.89	64.54
73.0	16.04	64.73
73.2	16.20	64.92
73.4	16.35	65.11
73.6	16.51	65.31
73.8	16.66	65.50
74.0	16.82	65.69
74.2	16.97	65.89
74.4	17.13	66.08
74.6	17.28	66.27
74.8	17.44	66.47
75.0	17.59	66.66
75.2	17.75	66.85
75.4	17.90	67.04

Sensor Temp (°F)	Percent RH	
	11.3%	75.3%
75.6	18.06	67.24
75.8	18.21	67.43
76.0	18.37	67.62
76.2	18.52	67.82
76.4	18.68	68.01
76.6	18.83	68.20
76.8	18.99	68.40
77.0	19.14	68.59
77.2	19.30	68.78
77.4	19.45	68.97
77.6	19.61	69.17
77.8	19.76	69.36
78.0	19.91	69.55
78.2	20.07	69.75
78.4	20.22	69.94
78.6	20.38	70.13
78.8	20.53	70.33
79.0	20.69	70.52
79.2	20.84	70.71
79.4	21.00	70.90
79.6	21.15	71.10
79.8	21.31	71.29
80.0	21.46	71.48
80.2	21.61	71.68
80.4	21.77	71.87
80.6	21.92	72.06
80.8	22.08	72.25
81.0	22.23	72.44
81.2	22.39	72.64
81.4	22.54	72.83
81.6	22.70	73.03
81.8	22.85	73.22
82.0	23.00	73.41
82.2	23.16	73.60
82.4	23.31	73.80
82.6	23.47	73.99
82.8	23.62	74.18
83.0	23.77	74.38
83.2	23.93	74.57
83.4	24.08	74.76
83.6	24.24	74.95
83.8	24.39	75.15
84.0	24.55	75.34

Sensor Temp (°F)	Percent RH	
	11.3%	75.3%
84.1	24.70	75.53
84.2	24.85	75.73
84.3	25.01	75.92
84.4	25.16	76.11
84.5	25.32	76.30
85.2	25.47	76.50
85.4	25.63	76.69
85.6	25.78	76.88
85.8	25.94	77.07
86.0	26.09	77.27
86.2	26.24	77.46
86.4	26.40	77.65
86.6	26.55	77.85
86.8	26.70	78.04
87.0	26.86	78.23
87.2	27.01	78.42
87.4	27.17	78.62
87.6	27.32	78.81
87.8	27.47	79.00
88.0	27.63	79.19
88.2	27.78	79.39
88.4	27.93	79.58
88.6	28.09	79.77
88.8	28.24	79.97
89.0	28.39	80.16
89.2	28.55	80.35
89.4	28.70	80.54
89.6	28.85	80.74
89.8	29.01	80.93
90.0	29.16	81.12
90.2	29.32	81.31
90.4	29.47	81.51
90.6	29.62	81.70
90.8	29.78	81.89
91.0	29.93	82.09
91.2	30.08	82.28
91.4	30.24	82.47
91.6	30.39	82.66
91.8	30.54	82.86
92.0	30.69	83.05
92.2	30.85	83.24
92.4	31.00	83.43
92.6	31.15	83.63

Sensor Temp (°F)	Percent RH	
	11.3%	75.3%
92.8	31.31	83.82
93.0	31.46	84.01
93.2	31.61	84.21
93.4	31.77	84.40
93.6	31.92	84.59
93.8	32.07	84.78
94.0	32.23	84.98
94.2	32.38	85.17
94.4	32.53	85.36
94.6	32.69	85.55
94.8	32.84	85.75
95.0	32.99	85.94
95.2	33.14	86.13
95.4	33.30	86.32
95.6	33.45	86.52
95.8	33.60	86.71
96.0	33.76	86.90
96.2	33.91	87.09
96.4	34.06	87.29
96.6	34.21	87.48
96.8	34.37	87.67
97.0	34.52	87.87
97.2	34.67	88.06
97.4	34.82	88.25
97.6	34.98	88.44
97.8	35.13	88.64
98.0	35.28	88.83
98.2	35.44	89.02
98.4	35.59	89.21
98.6	35.74	89.41
98.8	35.89	89.60
99.0	36.05	89.79
99.2	36.20	89.98
99.4	36.35	90.18
99.6	36.50	90.37
99.8	36.66	90.56
100.0	36.81	90.75
100.2	36.96	90.95
100.4	37.11	91.14
100.6	37.27	91.33
100.8	37.42	91.52
101.0	37.57	91.72
101.2	37.72	91.91

Appendix D: Determining the Dew Point in °C

Sensor Temp (°F)	Percent RH	
	11.3%	75.3%
19.4	-11.46	14.97
19.6	-11.37	15.07
19.7	-11.28	15.18
19.8	-11.19	15.29
19.9	-11.11	15.39
20.0	-11.02	15.50
20.1	-10.94	15.61
20.2	-10.85	15.72
20.3	-10.76	15.82
20.4	-10.68	15.93
20.6	-10.59	16.03
20.7	-10.51	16.14
20.8	-10.42	16.25
20.9	-10.33	16.36
21.0	-10.24	16.47
21.1	-10.16	16.57
21.2	-10.07	16.68
21.3	-9.99	16.79
21.4	-9.90	16.89
21.6	-9.82	17.00
21.7	-9.73	17.11
21.8	-9.64	17.22
21.9	-9.56	17.32
22.0	-9.47	17.43
22.1	-9.38	17.54
22.2	-9.29	17.64
22.3	-9.21	17.76
22.4	-9.12	17.86
22.6	-9.04	17.97
22.7	-8.95	18.08
22.8	-8.87	18.18
22.9	-8.78	18.29
23.0	-8.69	18.39
23.1	-8.61	18.51
23.2	-8.52	18.61
23.3	-8.43	18.72
23.4	-8.35	18.83
23.6	-8.26	18.93
23.7	-8.18	19.04
23.8	-8.09	19.15
23.9	-8.01	19.26
24.0	-7.92	19.36
24.1	-7.83	19.47

Sensor Temp (°F)	Percent RH	
	11.3%	75.3%
24.2	-7.74	19.58
24.3	-7.66	19.68
24.4	-7.57	19.79
24.6	-7.49	19.90
24.7	-7.40	20.01
24.8	-7.32	20.11
24.9	-7.23	20.22
25.0	-7.14	20.33
25.1	-7.06	20.43
25.2	-6.97	20.54
25.3	-6.88	20.65
25.4	-6.80	20.76
25.6	-6.72	20.86
25.7	-6.63	20.97
25.8	-6.54	21.08
25.9	-6.46	21.18
26.0	-6.37	21.29
26.1	-6.28	21.40
26.2	-6.20	21.51
26.3	-6.11	21.61
26.4	-6.03	21.72
26.6	-5.94	21.83
26.7	-5.86	21.93
26.8	-5.77	22.04
26.9	-5.68	22.15
27.0	-5.60	22.26
27.1	-5.51	22.36
27.2	-5.43	22.47
27.3	-5.34	22.58
27.4	-5.26	22.68
27.6	-5.17	22.79
27.7	-5.08	22.90
27.8	-5.00	23.01
27.9	-4.91	23.11
28.0	-4.83	23.22
28.1	-4.74	23.33
28.2	-4.66	23.43
28.3	-4.57	23.54
28.4	-4.48	23.65
28.6	-4.40	23.76
28.7	-4.31	23.86
28.8	-4.23	23.97
28.9	-4.14	24.08

Sensor Temp (°F)	Percent RH	
	11.3%	75.3%
28.9	-4.06	24.18
29.0	-3.97	24.29
29.1	-3.88	24.40
29.1	-3.80	24.51
29.2	-3.71	24.61
29.6	-3.63	24.72
29.7	-3.54	24.83
29.8	-3.46	24.93
29.9	-3.37	25.04
30.0	-3.28	25.15
30.1	-3.20	25.26
30.2	-3.11	25.36
30.3	-3.03	25.47
30.4	-2.94	25.58
30.6	-2.86	25.68
30.7	-2.77	25.79
30.8	-2.68	25.90
30.9	-2.60	26.01
31.0	-2.52	26.11
31.1	-2.43	26.22
31.2	-2.34	26.33
31.3	-2.26	26.43
31.4	-2.17	26.54
31.6	-2.09	26.65
31.7	-2.01	26.76
31.8	-1.92	26.86
31.9	-1.83	26.97
32.0	-1.75	27.08
32.1	-1.66	27.18
32.2	-1.58	27.29
32.3	-1.49	27.39
32.4	-1.41	27.51
32.6	-1.32	27.61
32.7	-1.23	27.72
32.8	-1.15	27.83
32.9	-1.07	27.93
33.0	-0.98	28.04
33.1	-0.89	28.14
33.2	-0.81	28.26
33.3	-0.73	28.36
33.4	-0.64	28.47
33.6	-0.56	28.57
33.7	-0.47	28.68

Sensor Temp (°F)	Percent RH	
	11.3%	75.3%
33.8	-0.38	28.79
33.9	-0.30	28.89
34.0	-0.22	29.01
34.1	-0.13	29.11
34.2	-0.04	29.22
34.3	0.04	29.32
34.4	0.13	29.43
34.6	0.21	29.54
34.7	0.29	29.64
34.8	0.38	29.75
34.9	0.47	29.86
35.0	0.55	29.97
35.1	0.63	30.07
35.2	0.72	30.18
35.3	0.81	30.29
35.4	0.89	30.39
35.6	0.98	30.50
35.7	1.06	30.61
35.8	1.14	30.72
35.9	1.23	30.82
36.0	1.32	30.93
36.1	1.40	31.04
36.2	1.48	31.14
36.3	1.57	31.25
36.4	1.66	31.36
36.6	1.74	31.47
36.7	1.82	31.57
36.8	1.91	31.68
36.9	1.99	31.78
37.0	2.08	31.89
37.1	2.16	32.00
37.2	2.25	32.11
37.3	2.33	32.21
37.4	2.42	32.32
37.6	2.50	32.43
37.7	2.59	32.53
37.8	2.67	32.64
37.9	2.76	32.75
38.0	2.84	32.86
38.1	2.93	32.96
38.2	3.01	33.07
38.3	3.09	33.18
38.4	3.18	33.28